Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	or(s): Perkins			28-Oct-20
Company/Owner:	Intermou	ıntain Gas Company	Unit/OPID:	8160
Inspection Type 9 Time /	I day)	Total In	spection Davis	
Inspection Type & Time (1	L day)	Total in	spection Days:	1
Standard: Construction:	1 Training:	(T)(D) Integrity Management:	Incident:	
M/M: Follow-up:	OQ:	Damage Prevention:	D&A:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
28 Oct 2020: (1.0 Construction) Observed a Das-co crew installing a new ¾" service lines at 4413/4429/4443/4459 W Sunny Cove, Meridian, Idaho. All procedures were followed. Typed up report. Areas observed during this project were: Excavating, line locating, pressure testing, EFV install, bedding/backfilling, riser install and purging Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project. Pictures of Job ticket.				
Corrective Action Required:		ow-up Required: Yes		Х
Yes No	X	7	by (date):	
Inspector (Lead):	Joans .		Date:	
Bruce Perkins	To The	#	10/28/2020	
Reviewer: Darrin Ulmer	1 and the	Hs.	Date: 20.20	